

The Boeing Company  
P.O. Box 3707  
Seattle, WA 98124-2207

WAD 6819  
10/9/07  
1000/0/07  
RECEIVED

October 8, 2007  
G-1241-WDE-196

Mr. Shawn Blocker  
RCRA Corrective Action, AWT-121  
U.S. Environmental Protection Agency, Region 10  
1200 Sixth Avenue  
Seattle, Washington 98101

10/8/2007

FILE COPY

FILE COPY



Subject: Notice of Field Work – Characterization of Caulk in Concrete  
Pavements Interim Measure Work Plan  
Boeing Plant 2, Seattle/Tukwila, Washington  
EPA ID No. WAD 00925 6819  
RCRA Docket No. 1092-01-22-3008(h)

Dear Mr. Blocker:

In accordance with Order Section 12.2, Boeing is providing this Notice of Field Work for purposes of implementing the subject Work Plan.

In accordance with the schedule provided in the subject plan, we will review existing data and prepare drawings during the week of October 8, and we expect to begin caulk descriptive characterization and sampling field work during the week of October 15. Unfortunately, and since the caulk characterization task is highly dependent on consistent weather conditions, we cannot now rely on favorable weather for this portion of the work. We will endeavor to complete descriptive characterization and sampling within eight weeks of the IM WP approval, which would be November 28, but will advise you of any necessary delays due to unacceptable weather conditions that may occur.

Please contact me should you wish to discuss or visit Plant 2 to observe this activity at any point so that I may arrange for a proper welcome and escort.

Sincerely,

*Will Ernst*

Will Ernst  
Project Coordinator; Environmental Remediation  
M/C 1W-12; 425.891.7724; 206.544.7297 (fax); william.d.ernst@boeing.com

cc: Hideo Fujita, Department of Ecology (by email)  
Brad Helland, Department of Ecology (by email)

USEPA RCRA



3017296